



TIKKURILA **MIRANOL** IMPACT-RESISTANT ALKYD PAINT / FULL GLOSS

DESCRIPTION	Thixotropic (gelatinous) alkyd paint with a mild odor.
RECOMMENDED USES	Freestanding furniture, objects, toys, tools, boats, bicycles, signs, etc.
PRODUCT FEATURES	For interior and exterior painting of wood and metal surfaces. See directions for use. Thixotropic Miranol is easy to apply. It does not sag and levels well.



TECHNICAL DATA	
Base paints	A BASE, C BASE
Colour Shades	Color cards: Feel the Color, Symphony Color System, Feel the Color 2020, Facade 760 colour collection, Color Now 2022, Deco Grey colour card Can be tinted in Tikkurila colors.
Gloss	High gloss.
Coverage	Metal surfaces: 12–14 m²/l. Smooth wood surfaces: 10–12 m²/l.
Can sizes	A BASE: 0.225 I, 0.9 I, 2.7 I, 9 I C BASE: 0.225 I, 0.9 I, 2.7 I, 9 I
Application method	Brush, roller or spray.
	Airless spraying - nozzle 0.009"–0.013" (0.230–0.330 mm) - thin 10–20% by volume.
	Conventional spraying - paint nozzle 1,4 mm - 1,8 mm - thin 25–35% by volume (DIN4 18–25 s) (when spraying, the dry paint film must not exceed 40 μm).
Drying time	Dust dry after 3-4 hours. Recoatable after approx. 24 hours.
Density (kg/l)	0.9–1.1 kg/l depending on the shade, ISO 2811
Weather resistance	Good
Chemical resistance	Resistant to vegetable and animal fats, lubricating oils and greases, turpentine, white spirit and denatured alcohol. Not resistant to e.g. thinner. SFS-EN ISO 2812.
Wash resistance	Good with all ordinary detergents, SFS-EN ISO 11998.
Heat resistance	Heat resistant up to 120 °C. Light tones will yellow slightly on surfaces that become warm. ISO 4211-3.
Volume solids (%)	50
Storage	Unaffected by cold storage or transportation.



MIRANOL

APPLICATION INSTRUCTIONS

Application conditions

The surface to be painted must be dry, the ambient temperature at least +5 °C and the relative humidity of air below 80%. Note! Under the conditions mentioned above, drying is notably slower than under standard conditions (+23 °C, relative humidity 50%). This especially affects dark shades tinted with Avatint pastes.

Surface preparation

Unpainted surfaces:

Remove all dirt, dust, grease, oil and rust.

Prime wood surfaces with Otex adhesion primer. Interior steel surfaces in dry conditions can be painted directly with Miranol, zink-coated and aluminum surfaces should be primed with Otex. Aluminum surfaces must be roughened before priming.

Previously painted surfaces:

Wash the surfaces with Maalipesu detergent, rinse carefully with water and let dry well. Remove any loose paint with a scraper and sand the entire surface. Remove the sanding dust. Use Lakkakitti to fill any holes and cavities. Use Otex to prime/undercoat surfaces that are in poor condition.

When painting with a bright red or yellow color, prime according to the object with Otex adhesion primer tinted to the same color.

Painting

Stir the paint thoroughly before use and, if necessary, thin with White Spirit 1050 for brush application and with Ruiskuohenne 1032 for spray application. Apply 1–2 coats by brush or spray.

Maintenance painting:

Surfaces painted with Miranol can be maintenance painted with a similar type of solvent-borne paint. See Pretreatment.

Cleaning of tools

Clean tools with White Spirit 1050 or Tikkurila Pensselipesu (Tool Cleaner). Clean tools with White Spirit 1050 or with Tikkurila Pensselipesu (Tool Cleaner).

Maintenance instructions

If needed, after approx. 1 month from painting, at the earliest: Clean the surface with a neutral (pH 6–8) dish washing solution and a soft brush, sponge or cleaning cloth. Clean very dirty surfaces with a mild alkaline (pH 8–10) washing solution and a cleaning cloth or sponge. Rinse the surface carefully.

After the surface treatment, surfaces must be handled with care for a few weeks, as the product will reach its final hardness and durability in about one month under normal conditions. If the surfaces need to be cleaned soon after finishing, clean them lightly with a brush or damp cleaning cloth.

Maintenance treatment

Maintenance painting: Surfaces painted with Miranol can be maintenance painted with a similar type of solvent-borne paint. See Pretreatment.



MIRANOL

Environmental protection and waste disposal

Avoid spillage into drains, water systems and soil. Destroy liquid waste according to the local regulations for hazardous waste. Recycle empty, dry cans or dispose them of in accordance with local regulations.

Health and Safety

Contains: hydrocarbons, C9-C11, n-alkanes, isoalkanes, cyclics, <2% aromatics. **Warning.** Flammable liquid and vapor. May cause drowsiness or dizziness. If medical advice is needed, have product container or label at hand. Keep out of reach of children. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Avoid breathing mist/vapors/spray. Use only outdoors or in a well-ventilated area. Warning! Hazardous respirable droplets may be formed when sprayed. Do not breathe spray or mist.





